




- | | |
|-------------------------|-------------------------------------|
| 1 / HANGER | 8 / SCREW NUT |
| 2 / HANGER CAP (20 Nm) | 9 / TAPER NUT |
| 3 / BEARING (24x15x5) | 10 / SPACER |
| 4 / BEARING (24x12x6) | 11 / SPACER (6x10x1t) |
| 5 / BEARING (10x22x6) | 12 / SCREW BOLT (M6x25L-P-S, 10 Nm) |
| 6A / PIVOT AXLE (10 Nm) | 13 / SCREW BOLT (M8x16L-M, 10 Nm) |
| 6B / PIVOT AXLE (14 Nm) | 14 / BEARING CUP |
| 6C / PIVOT AXLE (14 Nm) | 15 / C-RING |
| 7 / PIVOT (19 Nm) | 16 / SHOCK BOLT (10 Nm) |