



- | | | |
|------------------------|------------------------|------------------------------|
| 1 / HANGER | 8 / PIVOT AXLE / 14 Nm | 14 / SPACER (6x10x1t) |
| 2 / HANGER CAP | 9 / PIVOT | 15 / SCREW BOLT (M6x25L-P-S) |
| 3 / BEARING (24x15x5) | 10 / SCREW NUT | 16 / SCREW BOLT (M8x16L-M) |
| 4 / BEARING (24x12x6) | 11 / TAPER NUT | 17 / BEARING CAP |
| 5 / BEARING (10x22x6) | 12 / RING | 18 / C-RING |
| 6 / PIVOT AXLE / 14 Nm | 13 / SPACER | 19 / SHOCK BOLT |
| 7 / PIVOT AXLE / 10 Nm | | |